Exhibit D

Asbestos & Heavy Metal Paint Survey
Lemay Maintenance Facility
Salt Storage Buildings

MEMORANDUM

Missouri Department of Transportation
Construction and Materials
Central Laboratory

TO: Randall Glaser-6de

COPY:

FROM: Frank Reichart
Environmental Chemist

DATE: July 6, 2009

SUBJECT: Materials
Asbestos & Heavy Metal Paint Inspection
Route I-55OR
Job No. N/A
Parcel Lemay MT Lot-Salt Sheds
St Louis County

We are providing you with the results of the requested inspection on the above referenced property. The inspection report contains an asbestos and a heavy metals survey, unless otherwise requested. The asbestos inspection included sample collection of suspect asbestos-containing material and National Voluntary Laboratory Accreditation Program (NVLAP) accredited testing to confirm the presence of asbestos. This asbestos and heavy metal paint report includes four different report forms. Form T746 lists all of the samples taken during the asbestos inspection. Form T747 shows only those samples that tested positive for Category I nonfriable asbestos-containing materials that may remain in the structure during demolition, if kept adequately wet to avoid visible air emissions. Form T748 shows only those samples that tested positive for asbestos and require removal prior to demolition. Form C760 lists all paint samples taken during the heavy metal paint inspection and their metal content.

In accordance with the National Emissions Standard for Hazardous Air Pollutants (NESHAP), as well as city and county asbestos abatement regulations - Registration, Notification, and Performance Requirements, regulated asbestos-containing material (RACM) namely, Friable and Category II nonfriable, have a high probability of becoming friable under normal demolition forces. Practices and procedures for removal prior to demolition, disposal, and clearances should be in accordance with referenced regulations. Missouri Department of Transportation policy is to perform asbestos abatements in accordance with NESHAP.

In accordance with Missouri Department of Natural Resources' Technical Bulletin "Managing Construction and Demolition Waste" dated January 31 2003, a heavy metal paint inspection has been performed on the above referenced property. We are providing you with the results of this inspection. The inspection includes locating painted concrete, block and/or brick surfaces, sampling the painted surface(s) and testing the paint(s) to determine if hazardous heavy metals are present. Non-hazardous painted concrete, blocks, or bricks may be used as clean fill

materials, if properly handled. You must contact the Central Office Design Division for proper handling of the reported painted surfaces.

Although our survey included observing and sampling behind walls, above ceilings, beneath floors, etc., it is possible that potentially hidden asbestos-containing materials may exist within the structures. To our knowledge, we have located all suspect asbestos-containing and all painted concrete, block and brick surfaces. If suspect asbestos-containing materials or if painted concrete, block and/or brick surfaces are observed in addition to those reflected in this inspection report, then please advise us immediately so that we may schedule a follow-up inspection.

Should you have any questions regarding these reports, please contact me at (573) 526-4359.

db/dr
J:\barred\asbestos\District 6\Misc\fr907062 Lemay.doc
Attachments

Form T746
Rev. 04/2003

MISSOURI DEPARTMENT OF TRANSPORTATION
CONSTRUCTION AND MATERIALS
Asbestos Survey Report
All Suspect ACM

ROUTE: I-55 OR
MODOT JOB NO.: N/A
DISTRICT: 6
COUNTY: St Louis
DATE OF SURVEY: June 30, 2009
PARCEL NO.: Lemay MT Lot-Salt Sheds

SURVEYED BY: Frank Reichart and Diane Roegge
CERTIFICATION #: 7028020509MOIR11239, F.R.
CERTIFICATION #: 7028020509MOIR7165, D.R.
SITE ADDRESS: 4185 Hoffmeister Avenue, St Louis 63125
TYPE(S) OF STRUCTURE(S): 3-Bay Wooden Salt Shed (North) and 3-Bay Concrete/Wooden Salt Shed (South)

Sample ID	Type of Materials	Location of Material	Friability Category	Field Measure
	North Salt Shed			
9MD1R 482	Asphalt Rolled Roofing (Tan)	Roof, 1st Layer	N-ACM	
9MD1R 483	Asphalt Rolled Roofing (White)	Roof, 2nd Layer	N-ACM	
9MD1R 484	Asphalt Felt Material	Roof, 3rd Layer	N-ACM	
9MD1R 485	Asphalt Joint Compound	Roof, Seams	I NF	30 Sq. Ft.
	South Salt Shed			
9MD1R 486	Asphalt Roofing Shingles (Tan)	Roof, 1st Layer	N-ACM	
9MD1R 487	Asphalt Felt Material	Roof, 2nd Layer	N-ACM	

N-ACM = Non-Asbestos Containing Material I NF = Category I Nonfriable II NF = Category II Nonfriable F = Friable
NAFD = No Asbestos Fiber Detected * = Tested By Point Count Procedure

Form T747
Rev. 12/2005

MISSOURI DEPARTMENT OF TRANSPORTATION
CONSTRUCTION AND MATERIALS
Asbestos Survey Report
Nonfriable Asbestos-Containing Materials
(Abatement not required if not made friable during demolition.)

ROUTE:	I-55 OR	**TESTED BY:**	Frank Reichart and Diane Roegge
MODOT JOB NO.:	N/A	**CERTIFICATION #:**	7028020509MOIR11239, F.R.
DISTRICT:	6	**CERTIFICATION #:**	7028020509MOIR7165, D.R.
COUNTY:	St Louis	**SITE ADDRESS:**	4185 Hoffmeister Avenue, St Louis 63125
DATE OF TESTS:	July 6, 2009	**TYPE(S) OF STRUCTURE(S):**	3-Bay Wooden Salt Shed (North) and 3-Bay Concrete/Wooden Salt Shed (South)
PARCEL NO.:	Lemay MT Lot-Salt Sheds		

Sample ID	Type of Material	Location of Material	Friability Category	Field Measure	Asbestos Type	Percent
	North Salt Shed					
9MD1R 485	Asphalt Joint Compound	Roof, Seams	I NF	30 Sq. Ft.	Chrysotile	10-20
	South Salt Shed					
		None Located	I NF			

All necessary work to handle this material is the contractor's responsibility.

I NF = Category I Nonfriable

Form T748
Rev. 04/2003

MISSOURI DEPARTMENT OF TRANSPORTATION
CONSTRUCTION AND MATERIALS
Asbestos Survey Report
All materials requiring removal or special handling.

ROUTE:	I-55 OR	**TESTED BY:**	Frank Reichart and Diane Roegge
MODOT JOB NO.:	N/A	**CERTIFICATION #:**	7028020509MOIR11239, F.R.
DISTRICT:	6	**CERTIFICATION #:**	7028020509MOIR7165, D.R.
COUNTY:	St Louis	**SITE ADDRESS:**	4185 Hoffmeister Avenue, St Louis 63125
DATE OF TESTS:	July 6, 2009	**TYPE(S) OF STRUCTURE(S):**	3-Bay Wooden Salt Shed (North) and 3-Bay Concrete/Wooden Salt Shed (South)
PARCEL NO.:	Lemay MT Lot-Salt Sheds		

Bid Item No.	Sample ID	Type of Material	Location of Material	Friability Category	Field Measure	Asbestos Type	Percent
		North Salt Shed					
			None Located	F			
			None Located	II NF			
		South Salt Shed					
			None Located	F			
			None Located	II NF			

I NF = Category I Nonfriable II NF = Category II Nonfriable F = Friable * = Tested By Point Count Procedure

J:\BARRED\ASBESTOS\DISTRICT 6\MISC\LEMAY MT-SALT SHEDS.DOC

Form C760
Rev. 04/2003

MISSOURI DEPARTMENT OF TRANSPORTATION
CONSTRUCTION AND MATERIALS
Metals Survey Report of Painted Concrete, Block, Brick Surfaces

ROUTE: I-55 OR
MODOT JOB NO.: N/A
DISTRICT: 6
COUNTY: St Louis
SURVEYED BY: Frank Reichart
DATE OF SURVEY: June 30, 2009

TESTED BY: N/A
DATE OF TESTS: N/A
PARCEL NO.: Lemay MT Lot-Salt Sheds
SITE ADDRESS: 4185 Hoffmeister Avenue, St Louis 63125
TYPE(S) OF STRUCTURE(S): 3-Bay Wooden Salt Shed (North) and 3-Bay Concrete/Wooden Salt Shed (South)

Sample ID	Color/Location of Material/Substrate	Metals (ppm)							
		As	Cr	Pb	Cd	Se	Ba	Hg	Ag
	North Salt Shed								
	No samples taken. No painted surfaces located.								
	South Salt Shed								
	No samples taken. No painted surfaces located.								

All results are by XRF unless otherwise indicated: a = USEPA SW-846 Method 3050
b = USEPA SW-846 Method 7471